

mm

d	D	内孔公差 I.D. Tolerance F7	外径公差 O.D. Tolerance m6	L $\begin{matrix} -0.10 \\ -0.30 \end{matrix}$												
				30	35	40	50	60	70	80	100	120	130	140	150	
60	75	60 ^{+0.060} _{+0.030}	75 ^{+0.030} _{+0.011}	607530	607535	607540	607550	607560	607570	607580	6075100					
63	75	63 ^{+0.060} _{+0.030}	75 ^{+0.030} _{+0.011}					637560	637570	637580						
65	80	65 ^{+0.060} _{+0.030}	80 ^{+0.030} _{+0.011}				658050	658060	658070	658080						
70	85	70 ^{+0.060} _{+0.030}	85 ^{+0.035} _{+0.013}		708535	708540	708550	708560	708570	708580	6080100					
70	90	70 ^{+0.060} _{+0.030}	90 ^{+0.035} _{+0.013}				709050	709060	709070	709080						
75	90	75 ^{+0.060} _{+0.030}	90 ^{+0.035} _{+0.013}					759060	759070	759080	7590100					
75	95	75 ^{+0.060} _{+0.030}	95 ^{+0.035} _{+0.013}					759560	759570	759580	7595100					
80	96	80 ^{+0.060} _{+0.030}	96 ^{+0.035} _{+0.013}			809640	809650	809660	809670	809680	8096100	8096120				
80	100	80 ^{+0.060} _{+0.030}	100 ^{+0.035} _{+0.013}			8010040	8010050	8010060	8010070	8010080	80100100	80100120			80100140	
90	110	90 ^{+0.071} _{+0.036}	110 ^{+0.035} _{+0.013}	9011030			9011050	9011060	9011070	9011080	90110100	90110120				
100	120	100 ^{+0.071} _{+0.036}	120 ^{+0.035} _{+0.013}					10012060	10012070	10012080	100120100	100120120			100120140	
110	130	110 ^{+0.071} _{+0.036}	130 ^{+0.040} _{+0.015}							11013080	110130100	110130120				
120	140	120 ^{+0.071} _{+0.036}	140 ^{+0.040} _{+0.015}							12014080	120140100	120140120			120140140	
125	145	125 ^{+0.083} _{+0.043}	145 ^{+0.040} _{+0.015}								125145100	125145120				
130	150	130 ^{+0.083} _{+0.043}	150 ^{+0.040} _{+0.015}								130150100		130150130			
140	160	140 ^{+0.083} _{+0.043}	160 ^{+0.040} _{+0.015}								140160100				140160140	
150	170	150 ^{+0.083} _{+0.043}	170 ^{+0.040} _{+0.015}								150170100					150170150
160	180	160 ^{+0.083} _{+0.043}	180 ^{+0.040} _{+0.015}								160180100					160180150